




machine wash
maximum temperature 30 C
minimum agitation




machine wash
maximum temperature 40 C
minimum agitation




machine wash
maximum temperature 50 C
minimum agitation




machine wash
maximum temperature 30 C
medium agitation




machine wash
maximum temperature 40 C
medium agitation




machine wash
maximum temperature 50 C
medium agitation




machine wash
maximum temperature 30 C
maximum agitation




machine wash
maximum temperature 40 C
maximum agitation




machine wash
maximum temperature 50 C
maximum agitation




machine wash
maximum temperature 60 C
minimum agitation




machine wash
maximum temperature 70 C
minimum agitation




machine wash
maximum temperature 95 C
minimum agitation




machine wash
maximum temperature 60 C
medium agitation




machine wash
maximum temperature 70 C
medium agitation




machine wash
maximum temperature 95 C
medium agitation



machine wash
maximum temperature 60 C
maximum agitation



machine wash
maximum temperature 70 C
maximum agitation



machine wash
maximum temperature 95 C
maximum agitation



do not wash
be cautious when
treating in wet stage



handwash only
maximum temperature 40 C
handle with care



do not tumble dry



can be tumble dried



can be tumble dried on a low heat setting



can be tumble dried on a high heat setting



do not use chlorine-based bleach



suitable for dry cleaning with
special treatment, advice should
be sought from a professional
dry cleaner



suitable for dry cleaning



suitable for dry cleaning using
all solvents



suitable for dry cleaning using
solvents R113 and hydrocarbon



suitable for dry cleaning using
solvents R113 and hydrocarbon
advice should be sought from a
professional dry cleaner



do not dry clean



cool iron (maximum 110 C)



warm iron (maximum 150 C)



hot iron (maximum 200 C)



do not iron



chlorine-based bleaching allowed